



NOTES

n1. Lubricate O-Ring with Tribolube 71 grease (pos.513) before assembling.

Pos. No	Title	Part No	Qty
D4	O2 MONITOR ELECTRONICS UNIT	ORM8110	1
75	KNOB	ORM8021	2
76	LOCK RING	ORM8024	1
78	RING	ORM8042	1
354	MONITOR HOUSING	ORM8016	1
356	MONITOR CAP	ORM8017	1
357	SENSOR HOLDER	ORM8018	1
358	MONITOR CAP NUT	ORM8023	1
513	Tribolube 71 grease		
564	O-Ring BS150		1
570	O-Ring COG (80x2,5)		2
[L3]	O2 sensor PSR11-39-DL	See O2 EL BOM	3

Units of measurement	mm UNLESS OTHERWISE STATED	Mass	0,205 kg	Format	ISO A3	Designed by	S.Belousov	Changed by	-	Approved by - date	A.Bogatchev	Filename	ORM8100B.dwg	Date	05.08.2009	Scale	1:2
Material				Projection		<b>DEEP LIFE LTD</b> Strictly Commercial-in-Confidence, copyright (c) 2009. Copying prohibited except as provided for under written contract with Deep Life Ltd.				Title/Name <b>ASSY OF PP02 MONITOR</b>		Drawing number <b>ORM8100</b>		Edition B	Sheet(s) 1(1)		